



	VAIS Humidity and Ter For high temperat Valid from: Octobe	perat res ar	tur nd	e Pr													Probe type	Probe cable	Sensor type	Filter type	Sensor purge	RS-485 baud rate	Data, Parity, Stop bits	Modbus address	Reserved	Installation accessory	Connection cable
	Order code															НМРХ	ζ 5								0		
1	Probe type																										
_												istal	lation				5										
2	Cable length bet	een p	pro	bel	nead	d ar	nd p	orob	be be	ody	,							~									
	2m																	C D									
3	10 m																	D									
	Sensor type	can R	22 6	com	inoc	sita	eon	eor	· all	0.00	e eo	neo	r purg	<u>م</u>					1								
		cap R			-				-		3 30	1150	purg	C					2								
4	Filter type	cap n	12 3	50113	<u>, sor</u>	110	301	1301	pu	ige									-	1							
·		red st	taiı	nles	s st	teel	filte	ər						sp	are:	HM47	280	SP		в							
5	Sensor purge, de													-1-							1						
		on, o							qui	red	(sel	ecti	on 3)								0						
	Purg			•					•		`		,								1						
6	RS-485 baud rate																					-					
	1) 1920) bps	ι	ise \	<i>w</i> ith	Ind	ligo t	tran	smit	tters	5											Α					
	9600																					В					
7	Data, Parity, Stop																										
	1) 8 , N ,		ι	ise \	with	Ind	ligo t	tran	smit	tters	5												0				
	8, E,																						2				
	8, O,	1																					4				
8	Modbus address																										
	1) 240		ι	ise \	Nith	Ind	ligo t	tran	smit	tters	5													A			
	110																							В			
	120																							C			
	130																							D			
9	Reserved None																								0		
10	Probe mounting		601	~																					U		
10	None		301	-	or in	stal	llatio	n in	n evi	istini	a m	ount	ing fla	nae												0	
	-	ting fla	land		<i>•</i> 1 111	5.01				Sunt	9 110	Juni	ing na	,gc			sn	are	. 21	069	96					F	
11	Connection cable		ang	,-													30	a, c.	1	503						,	
``	None																										0
		with o	ope	n wi	res												sp	are	: 22	2326	535	P					1
		with o																		654							2
L	1) Factory pre-set					l in t	the f	field	with	hag	corv	ice c	ahla (P/N I	ISB	2)	575										

1) Factory pre-set, can be changed in the field with a service cable (P/N USB2)

Probe can be connected to INDIGO series of transmitters regardless of the output configuration.

Selections in bold are included in the prices of the basic versions.

Selections in italic are available at an extra price.

Example of order code with typical settings:

For use with INDIGO transmitters	HMPX	5	С	1	В	0	Α	0	Α	0	F	0
For use with Modbus RTU	HMPX	5	С	1	В	0	Α	0	Α	0	F	2